


EmaZys Technologies

PV Analyzer Z200 String Tester Report

Basic information

Test carried out by:
 Instrument operator:
 PV site address: Vejle
 PV string: Bottom silicon
 Date: 12-09-2018
 Time: 12:07:30
 Number of PV modules in string: 12
 Instrument Name: Z200-R1E00011612002
 Installed software version: 3.5.28

Results



Results

Open circuit voltage: 429.7 V
 Short circuit current: 3.3 A
 Low frequency norm: 6 Ω
 Low freq norm with load: 14 Ω
 Rs: 8 Ω
 Isolation Resistance (R_{ISO}): > 40 M Ω
 Estimated position of R_{ISO} :

String Test Conclusion

This function performs several tests to give a general health status of the PV string.

Test successfully finished

- Verify measured data against expected values.

Field Notes: Looks good

Final Comments: